



Local  
CMS#

CMS#

17091337 PERMIT


**CenturyLink Constant Job Order/Maintenance Work Authorization**

Company T866 Exchange 579 Osseo Service Order# \_\_\_\_\_  
 Work Activity Drop-Buried Copper Capital x Maintenance \_\_\_\_\_  
 Customer Name Maricela ADAYA GUTIERREZ Phone# 763-315-5403  
 Address 9905 107th Pl N One Call Ticket# \_\_\_\_\_  
 Location/Directions Brooklyn Park MN  
 Description of Work or Special Instructions Plow 250 ft from Ped to Nid

DOR/TOG Yes \_\_\_ No x Permit: Yes \_\_\_ No x Bore: Yes x No \_\_\_ CBR# \_\_\_\_\_  
 Employee Name Kris Townsend Employee Contact# 612-4303133

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_  
 Damaged facility # 125904  
**SKETCH** Tax Code \_\_\_\_\_ |  
-N-  
|



Originated By: <u>Evans</u>	Date: <u>9/9/16</u>	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	_____
Inspection notes: _____	_____		