


Revised 4-6-18		CMS#	18231565 - PERMIT		
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange Name	MAPLE GROVE	Service Order#	1519843092
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	Maggie Pearson		Phone#	763-425-4754	
Address	15439 108th ave N		One Call Ticket#		
City & Zip	Dayton, MN				
Location/Directions					
Description of Work or Special Instructions					

Held Order	N	Permit:	Y	Bore:	Y	CBR#	763-807-0943
Tech Name and Tech #	Les Peterson AA09419			Employee Contact#			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot#	33	SEB3-22	BSW-3 & plow plcmt	
		SEB3-22T	BSW-3 & hand dig plcmt	
Ped#	15482	SEPCUTOVER	CUTOVER BSW	
Parish/County	Hennepin	BM83	BSW guard at house	1
		XXSEB-GL	Remove temp drop	550
Township:		BM61(1.25)SEB	BSW Bore footage	100
Section		SEBO PER FT LBR	Fiber & plow plcmt	60
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt	
		SEB6-22	BSW-6 & plow plcmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	1
		BM61(3)D-Rock CBL	Rock Boring	
		Permit	Permit	1
Nearest cross st.	Sundance BLVD N		Plat Page	Map#



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	