Century Link	Local CMS#	99		RDER PERMIT	
	CenturyLink Constant J	Job Order/Mainten	ance Mork A.AL	S-1-2/12	
Company Work Activity Customer Name Address Location/Directions Description of Work or	Drop-Buried Copper Keri Hedland 11816 85th, Pi. W.	Osseo Maple Grove	Capital x	Service Order#	416-319
DOR/TOG Employee Name Sketch (Include Line & Pedestal)	Yes No x Permit: Yes Brandon Smith Material/Labor Description		No X Employee Contact# Est Actual Qty. Qty	Placed by	1562
Line Ped# Parish/County Hennipen Township:			aty. aty	(Foreman/Crew Name)	
Section Range GPS Reading					
Nearest cross st. Damaged facility # SKETCH		965-9	Plat Page	Map#	_N -
	11442		11828		
-	11838	1	Dare 11824	a sai	10.
	11434	11	11820	time to	
	11830	7	11816	11800	3
		8	5+h. Pl. N.	<u></u>	
riginated By: uthorized By: (APS) uthorized By: (AOM)	Date: Date: Date:	Completed By	<i>Y</i> :	Date:Date:	