			Local CMS#											
			Exch#											
					nturyLink BSW O	/ Order/Maintenar			ance					
Company		T600 Exchange			Capital			Service Order						
Work Activity		had a second					Cap	pital	N	Dh	Mainten		Y	~
Customer Name		brian grant 10885 quaker In n							0.000		one#	76	3-315-460	3
Address							Une C	all Ticke	τ#					
City & Zip Location/Directions		maple grove GPS						_			-	-		
Description of Work			ions											
see sketch for detai														
Held Order ?		NO	Bore: N	: NO				CBR# 612-965-3228						
Employee Name		NO Permit: NO MER064519			Boloi	-	Employee Conta							
		Material/Labor			Units		Est Actual			Placed by				
(Include Cntr Line & Pedestal)		Description		1000	Notes		ty.	Qty	(Foreman/Cre					
Cntr Line foota	33	SEB3-22	·		Place 3 pair BSW		<i></i>				(		- /	
		SEPCUTOV	'ER		CUTOVER BSW			1						-
Parish/County	Hennepi	XXSEB-GL			BSW guard at house Remove temp drop									
Township:		BM61(1.5)	D		BSW Bore required			90						
Section	na	SEB3-22T			Hand Dig									
Range	na	SEBOP2			Fiber Drop			245						
Nearest cross st.	GPS						Plat	Page	GPS		Map#	GP	s	
Damaged facility #	015						That	Tuge	015		Widp#	01	0	
SKETCH														
	100	3			1090	in av	en.		1	J	usun <i>l</i> ave	N (		
TERMINA THER SP		10865		5 8 9 •••••••••••••••••••••••••••••••••••		5 Que	10395	IN 5536	2				108th PI N	AND STAR STAR
Originated By: Authorized By: (APS		AA10109		map to ce: 245	·	1 Ur ted B	nited St	10810 PU		Privacy S	end feedback	50 ft L 4:2	7 PM 8/2021 ↓	
Authorized By: (APS				Date: Date:		cu by	•					- Date:		
Inspection Notes:	,		Metro		@centurylink.com									
1. Distance of the	e burv in	Right-of-W	1	(		B. Dist	tance	e to the	neare	st inters	ection			
2 Distance from t										e marker				