

MN Metro

CMS 21167511 - HELD

Revised 3-10-2000 State

CenturyLink BSW Order/Maintenance Work Authorization

Company: Exchange Name: Service Order: 00134471

Work Activity: SN-152609 Capital: Y Maintenance: NJ

Customer Name: ERN SCHEER Phone#: 1000284730

Address: 10423 108th Ave N One Call Ticket#

City & Zip: Maple Grove, 55369

Location/Directions:

Description of Work or Special Instructions: Over 119 feet under 2 driveways to protect by line then dig the remaining 70 feet to west side of house

Work Order: Y N Permit: Y N Bore: (2) N CSR#: 763-486-6084

Tech Name and Tech #: LORRY MATSON - 117th Ave AD00432 Employee Contact#: 651-308-2297

Material/Labor Units	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Line	SE83-22	BSW-3 & plow picmt		
	SE83-22T	BSW-3 & hand dig picmt		
	SEPCUTOVER	CUTOVER BSW		
	BM83	BSW guard at house		
	K052B-0L	Remove temp drop		Footage when temp can't be used
	BM81(1.25)SEB	BSW bore footage	119	
	SE80 PER FT LBR	Fiber & plow picmt	124	
	SE80 PER FT LBT	fiber & hand dig picmt		
	SE86-22	BSW-6 & plow picmt		
	BM015/808	Ground Rod		
	Trip Charge	Trip Charge		
	Permit	Permit		

NEAREST CROSS ST: _____

Page _____

Any placement within the ROW requires a permit



Originated By: _____ Date: _____ Completed By: _____ Date: _____

Authorized By: (SRO) _____ Date: _____ Inspected By: _____ Date: _____

Authorized By: (MRO) _____ Date: _____

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker