b.	Century	link
4	- Cortury	FILLS

Local CMS#

CMS#

F	CenturyLink Const	tant Job Order/Ma	aintenance V	Vork Autl	norization	
Company Work Activity Customer Name Address Location/Directions Description of Work or S	Drop-Buried Copper Megan Thomas 6700 Kentagan Linland	Ln. N., Maple		apital <u>x</u> One	Service Order# Mainten Phone# Z e Call Ticket#	ance
DOR/TOG		t: Yes x No Bo	ore: Yes	No X		
Employee Name	Brandon Smith		TWO STREET, SQUARE, SQ	oyee Contac	AND RESIDENCE OF THE PARTY OF T	OF THE OWNER OF THE OWNER OF THE OWNER, THE
Sketch (Include Line & Pedestal) Line Ped# Parish/County Hennipen Township:	Materia Description	al/Labor Units Notes	Est Qty.	Actual Qty	Place (Foreman/Cr	50
Section						
Range GPS Reading						
Nearest cross st. Damaged facility # SKETCH		_	Plat	Page	Map# _	
Originated By:		Inland Min. N.	731: 114802 731:	2 Drop		
Originated By:			ompleted By: spected By:			Date: Date:
Authorized By: (APS) Authorized By: (AOM) Inspection notes:		Date:ini	ъресіец ву:			Date.