Revised 4-6-18					CMS#		19058866

CenturyLink BSW Order/Maintenance Work Authorization

Company	T600	Exchange Name	MAPLE GROVE			Service Order#	
Work Activity	Fiber-Buried			Capital	Y	Maintenance	
Customer Name	Steve Ripsin				Phone#		7633150015
Address	9934 107th Pl N				One Call Ticket#		
City & Zip	Maple Grove MN						
Location/Directions							
Description of Work or Special Instructions			Plow 125 ft of fiber from ped to nid. Bore 90 ft right of way bore required				

Held Order			N	Permit:	Y		Bore:	Y			CBR#	6512603676
Tech Name and Tech #	Don Evans							Employee Contact#				6124303133

Sketch	Material/Labor Units		Footage/Quanity	Comments
(Include Cntr Line & Pedestal)	Description	Notes		
Cntr Line footage 33	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop	1	
Township:	BM61(1.25)SEB	BSW Bore footage	90	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	35	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	BM61(3)D-Rock CBL	Rock Boring		
	Permit	Permit	1	
Nearest cross st.			Plat Page	Map#

9934

Plow 35 ft

Bore 90 ft

Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	