MPGR095CA001
MPGR095CA003
MPGR095DA004
MPGR095DA001
MPGR095DA002
MPGR095DA003
MPGR096DA002
MPGR096DA001
MPGR096BA001
MPGR096AA006
MPGR096AA005
MPGR096AA004
MPGR096BA003

FIBER NOTE: JB00001339825 REPLACE PIGTAIL WITH 12CT

FIBER NOTE: JB00001339825 SP.MNMG.0260 PLACE NEW 1X12 RPHY MUX CH50-61 SPLICING REQUIRED

FIBER NOTE: JB00001339825 UPGRADE NODE (DC201) MNMPGR095 TO 1X2 RPHY MNMGD04U00 SPLICING REQUIRED

FIBER NOTE: JB00001339828 THIS JOB IS CONTINGENT UPON JB00001339825

FIBER NOTE: JB00001339828 SP.MNMG.0260 TIE INTO PROPOSED 1X12 RPHY MUX CH50-61 SPLICING REQUIRED

FIBER NOTE: JB00001339828 SP.MNMG.0261 SPLICING REQUIRED

FIBER NOTE: JB00001339828 UPGRADE NODE (DC202) MNMPGR096 TO 1X2 RPHY MNMGD05200 SPLICING REQUIRED

FIBER NOTE: JB00001339828 REPLACE PIGTAIL WITH 12CT

MNMGD04U00A MNMGD04U00B MNMGD04U00C MNMGD04U00D

MNMGD05200A MNMGD05200B MNMGD05200C MNMGD05200D

P001 90V

107th Pl N N
107th Ave N N
106th Pl N N
106th Ave N N
Nathan Ln N N
Zopfi Way W N
Zopfi
Lancaster Ln N N
Monticello Ln N N

MNMGD05200
MNMG
MAPLE GROVE, MN

Rev	Date	Description
01	2/8/23	DSN NOS / JB00001339828 / MP (QUASAR)

COMCAST