Revised 03-10-2021	**State**	MN	**Contractor**	MN Metro	**CMS#**		23133237

CenturyLink BSW Order/Maintenance Work Authorization

Company			Exchange Name	MPGVMNXA			Service Order#	sa-9070323
Work Activity		**Fiber-Buried**			Capital	Y	Maintenance	N
Customer Name		zach lauer				Phone#		(150) 009-2554
Address		6410 archer ln n				One Call Ticket#		
City & Zip		maple grove, mn 55311						
Location/Directions								
Description of Work or Special Instructions			bury permanent fiber service wire					
Held Order		N	**Permit:**	y	**Bore:**	y	CBR#	3203101253
Tech Name and Tech #		ryan peterson 954			Employee Contact#		7639101584	

Sketch		Material/Labor Units		Footage/Quantity		Comments	
(Include Cntr Line & Pedestal)		Description	Notes				
Cntr Line foota		SEB3-22	BSW-3 & plow plcmt				
		SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	6434 archer ln	SEPCUTOVER	CUTOVER BSW	1			
Parish/County		BM83	BSW guard at house	1			
		XXSEB-GL	Remove temp drop	400	Footage when temp can't be re-used		
Township:	mpl grv	BM61(1.25)SEB	BSW Bore footage	40			
Section		SEBO PER FT LBR	Fiber & plow plcmt				
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt	110			
		SEB6-22	BSW-6 & plow plcmt				
		BM2(5/8)(8)	Ground Rod				
		SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit		
		Permit	Permit		Any placement within the ROW requires a permit		
Nearest cross st.		yuma ln		Plat Page		Map#	

Originated By:		Date:		Completed By:		Date:
Authorized By: (SRO)		Date:		Inspected By:		Date:
Authorized By: (MRO)		Date:				

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	