

5-17 →
5-15 → FR submitted

J.T. 24203

Comcast

Plant Maintenance Request **V5** Job number **NW512**
 Node DA83 City maple grove Date 5/10/2017
 Address 8508 Zanzibar Ln N Cross Street Weaver lake rd
 Maint tech Name: Nathan Krick Tech # 1570 Phone: (612) 875-6664

Span type span (temped) Span (no temp) Digup Other Spring

Priority 1 a.) Customer Impacting Issue b.) Vulnerable temp c.) TIE related ticket
 2 a.) Aerial temp cables b.) Any temp - no liability issues
 3 a.) Identified cables - no customer impact b.) Leaks - no customer impact

Work is needed : ASAP Normal

Work is a : Cable Replacement Broken Lashing Pole Transfer Damaged Ped
 Utility Violation Storm Damage Leakage Other

MDU? (Attachments, lockboxes, cable on the roof) Yes No

Type of Cable Aerial UG Bare UG Duct Self Support Size: 0.625

Footage: Aerial _____ Underground 212'

Bore Required Yes No If yes, what type and how many _____

Is there fiber in the package? Yes No How Many Fibers? _____

Cause for referral: RTM Leakage Rapid Resolve (Flux) Damage/Outage NH/MH LPI
 (check one) Priority plant fault Service Call Alert PI Ticket Other CM Suckout

Explain Damage:

Cable is damaged in multiple spots. Main cable damage is directly under tree. Would have to cut multiple tree branches to get enough room for dig up.

Maintenance Department Use Only

Date Received _____ Capitol Yes No Maint complete
 Total Tech Hours _____ Techs _____

A Highlighted plant map must be attached

To help expedite this maintenance request, information on this form needs to be filled out completely and signed by a technician and a supervisor requesting the repair.

Tech Signature Nathan Krick Tech # 1570 Date 5/10/2017
 Supervisor Signature _____

Construction Department Use Only

Date received _____ Project # _____ Construction Completed
 Coordinator Signature _____ Supervisor Signature _____

