
			Loc	:h#				CMS#			74705		MIT		
				Ce	nturyLink BSW (Ord	er/Ma	intena	ance	Work A	Authoriz	ation			
Company		T600	Exchange							Service	Order#	1387717232			
Work Activity				•			Capital Y			Maintena	ance N				
Customer Name		MATTHEW BAKKER							Phone#			763	763-496-1959		
Address		17273 73RD PL N						One Call Ticket#							
City & Zip		MAPLE GROVE													
		GPS													
Description of Wor	k or Spec	ial Insti	ructions												
•				ORES AND	4 30' DRIVEWAY BO	RES									
Held Order ?				NO				952-221-	21-5984						
		MER064519					Employee Contact#				7632288645				
Employee Name	Material/Labor Units					Est Actual				Placed by					
(Include Cntr Line & Pedestal)		Description Notes				Qty.	Qty		(Foreman/Crew Name)						
Cntr Line foota 33		SEB3-22		Place 3 pair BSW		Qty.	Qty	(Foreman/C		(Foreman/Cr	ew manne,	1			
	G HOUSE		_		CUTOVER BSW										
Parish/County	Hennepi	BM83			BSW guard at house	9									
, , , , , , , , , , , , , , , , , , , ,		XXSEB-	GL		Remove temp drop										
Township:	na	BM61(:	1.5)D		BSW Bore required										
Section	na	SEB3-2	2T		Hand Dig										
Range	na	SEBOP2	2		Fiber Drop										
													<u> </u>		
											1				
Nearest cross st. GPS							Plat	Page	GPS		Map#	GPS			
Damaged facility #	:														
SKETCH															



Originated By: MER064	519	Date:	8/4/16	Completed By:		Date:		
Authorized By: (APS)		Date:		Inspected By:		Da	ate:	
Authorized By: (AOM)		Date:		_				
Inspection Notes:	BSW@c	enturylin	k.com					
1. Distance of the bury in Right-of			3. Distance	ction				
2. Distance from the terminal to th		•	4. Nearest		•			
•	•				•	•		