Revised 4-6-18									CMS#	18136439 PERMIT				
				Cen	tury	Link BSW O	der/N	/lainten	ance Wo	rk Au	thoriza	ition		
Company	T600 Exchange Name MAPLE GROVE								Service Order#					
Work Activity	Fiber-Buried							Capi	tal	Y Maintenand		ance		
Customer Name	Daniel I	Daniel Barrera								<u> </u>	Pho	one#	7634209585	
Address	8227 D	8227 Deerwood Ln N							1	One Call Ticket#				
City & Zip	Maple (Maple Grove Mn											<u> </u>	
Location/Directions														
Description of Work or Sp	ecial Instr	uctions		Plo v	/100	ft of fiber from p	ed to N	lid One h	ore requir	ed				
2 documentarior realities of	ooiai ii ioti	40110110				it or insortion p	00 10 11		oro roquii	- u				
Held Order		N	Permit:	Υ		Bore:	Υ				CBR#	61255920	035	
Tech Name and Tech #	Don Evans							Employee Contact#		#		6124303133		
Sketch		Material/Labor Units						Footage/Quanity						
(Include Cntr Line & Pedestal)	Description				Notes					Comments				
Cntr Line foota 33	SEB3-22				BSW-3 & plow plcmt									
	SEB3-22T				BSW-3 & hand dig plcmt									
Ped#	SEPCUTOVER				CUTOVER BSW			1						
Parish/County	BM83					BSW guard at house			1					
		XXSEB-GL			Remove temp drop				1					
Lownship:		BM61(1.25)SEB				BSW Bore footage			65					
Section		SEBO PER FT LBR				Fiber & plow plcmt			35					
Range	_	SEBO PER FT LBR T			Fiber & hand dig plcmt									
	SEB6-22				BSW-6 & plow plcmt									
		(-, -,(-,				Ground Rod								
						Trip Charge			1					
		BM61(3)D-Rock CBL				Rock Boring								
Permit					Pern	nit		1						
Nearest cross st.								Pla	t Page	I		Map#		

Estimated Cost

