


Lifetime Fitness
8001 Forestview Ln. N
Maple Grove, 55369
SM 035075

Node: MNMPGR102
Legacy: D-B16-1



fault component added

PWR:	MNMPGR102CA003
MPGR102CA003	
MEGR102CP001	
SA/SAGM - LEM	32.2
SA/SAGM - LEM	26.2
FORWARD PAD/EQ	49.0
FORWARD PAD/EQ	45.4
FORWARD PAD/EQ	36.5
RETURN PAD/EQ	0750.0
RETURN PAD/EQ	0750.0
INTERSTAGE PAD/EQ	2
18.0/18.0	28.3/26.8
89.2V	A

PWR:	MNMPGR102CA002
MPGR102CA002	
MEGR102CP001	
SA/SAGM - LEM	34.7
SA/SAGM - LEM	31.9
FORWARD PAD/EQ	49.0
FORWARD PAD/EQ	45.4
FORWARD PAD/EQ	36.5
RETURN PAD/EQ	0750.0
RETURN PAD/EQ	0750.0
INTERSTAGE PAD/EQ	2
18.0/18.0	22.6/20.5
89.2V	A