


Revised 4-6-18		CMS#	18218365	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	T600	Exchange Name	OSSEO	
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	AYMAN SHAKER		Phone#	7634242870
Address	11667 85TH PL N		One Call Ticket#	
City & Zip	Maple Grove MN			
Location/Directions				
Description of Work or Special Instructions				
Held Order	N	Permit:	Y	Bore: Y
Tech Name and Tech #	Roy Miller ab62842		Employee Contact#	612-219-9122
CBR#	510-672-5077			
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	33	SEB3-22		BSW-3 & plow plcmt
		SEB3-221		BSW-3 & hand dig plcmt
Ped#	11635	SEPCUTOVER	1	CUTOVER BSW
Parish/County	Hennepi	BM83	1	BSW guard at house
		XXSEB-GL		Remove temp drop
Township:		BM61(1.25)SEB	130	BSW Bore footage
Section		SEBO PER FT LBR		Fiber & plow plcmt
Range		SEBO PER FT LBR I	45	Fiber & hand dig plcmt
		SEB6-22		BSW-6 & plow plcmt
		BM2(5/8)(8)		Ground Rod
		Trip Charge	1	Trip Charge
		BM61(3)D-Rock CBL		Rock Boring
		Permit	1	Permit
Nearest cross st.	ForestView LN		Plat Page	Map#



Originated By:	Roy Miller	Date:	11/14/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:				Date:	
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					