Revised 4-					CMS#		19058546								
				Cen	tury	_ink BS	W Or	der/N	laintena	nce Wo	rk Αι	ıthoriza	ation		
Company	T600	T600 Exchange Name MAPLE GROVE										Service Order#			
Work Activity	Fiber-B	Fiber-Buried							Capit	al	Υ	Maintenance			
Customer Name	Edwin 7	Edwin Taylor									1	Ph	one#	7634	25659
Address	10775 1	10775 102nd ave n									One Call Ticket#				
City & Zip	Maple (Maple Grove MN													
Location/Directions															
Description of Work or S	necial Inst	ructions		Plow	215	it of fiber f	rom n	ed to r	id 165 ft	right of wa	y hor	a require	d		
Description of Work of S	Jeciai ilisti	uctions		I IOW	213	t of fiber i	ioni p	eu io i	iiu. 105 it	rigiti or wa	ay DOI	e require	u		
Held Order		N Permit: Y			Bore: Y						CBR# <mark>7634256598</mark>				
Tech Name and Tech #	Don Eva	Don Evans								e Contact#	6124303133				
Sketch		Material/Labor Units													
(Include Cntr Line & Pedestal)		Description				Notes				Footage/Quanity		Comments			
Cntr Line foot: 33	SEB3-22	SEB3-22				BSW-3 & plow plcmt									
	SEB3-22	SEB3-22T				BSW-3 & hand dig plcmt									
Ped# 125702		SEPCUTOVER				CUTOVER BSW				1					
Parish/County	BM83				BSW guard at house					1					
	XXSEB-0	XXSEB-GL				Remove temp drop				1					
Township:	BM61(1	BM61(1.25)SEB				BSW Bore footage				65					
Section		SEBO PER FT LBR				Fiber & plow plcmt									
Range		SEBO PER FT LBR T				Fiber & hand dig plcmt				50					
	SEB6-22	SEB6-22				BSW-6 & plow plcmt									
	BM2(5/	BM2(5/8)(8)				Ground Rod									
		Trip Charge BM61(3)D-Rock CBL				Trip Charge Rock Boring			1						
	BM61(3														
	Permit				Permit										
	Permit	<u>.</u>			Perm	it				1					

