

Revised 1-15-2019		CMS#		19095787 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T866	Exchange Name	OSSEO - OSSEMNXO	Service Order#	
Work Activity	Fiber-Buried	Capital	N	Maintenance	Y
Customer Name	HARLAN C & MAR HUSTED			Phone#	7634255307
Address	10698 BOUNDARY CREEK TERR N			One Call Ticket#	na
City & Zip	MAPLE GROVE, MN				
Location/Directions	GPS				
Description of Work or Special Instructions	See sketch for details				
Held Order	N	Permit:	Y	Bore:	Y
Tech Name and Tech #	AA10109		Employee Contact#	763-228-8645	
Sketch	Material/Labor Units			Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line foot#	33	SEB3-22	BSW-3 & plow plcmt		
		SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	splitter	SEPCUTOVER	CUTOVER BSW	1	
Parish/County		BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop	375	Footage when temp can't be re-used
Township:	NA	BM61(1.25)SEB	BSW Bore footage	80	
Section	NA	SEBO PER FT LBR	Fiber & plow plcmt	125	
Range	NA	SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge	1	
		Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.		NA	Plat Page	NA	Map# NA

Originated By:	AA10109	Date:	5/31/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					