

Revised 1-15-2019				CMS#		19119145	
CenturyLink BSW Order/Maintenance Work Authorization							
Company		T866 Exchange Name		MAPLE GROVE - MPGVMNXA		Service Order# 1544943702	
Work Activity		Fiber-Buried		Capital Y		Maintenance	
Customer Name		KYLE YAEGER		Phone#		763-416-0541	
Address		7548 WALNUT GROVE LN N		One Call Ticket#			
City & Zip		Maple Grove					
Location/Directions		near Rush Creek Golf Course					
Description of Work or Special Instructions		new biber drop bore driveway and plow..cutover temp					
Held Order		y		Permit: y		Bore: y	
Tech Name and Tech #		Ryan Einerwold		Employee Contact#		763-464-7242	
Sketch		Material/Labor Units		Footage/Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes			
Cntr Line foot		SEB3-22		BSW-3 & plow plcmt			
		SEB3-22T		BSW-3 & hand dig plcmt			
Ped#		SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		BSW guard at house		1	
		XXSEB-GL		Remove temp drop		150	
Township:		BM61(1.25)SEB		BSW Bore footage		90	
Section		SEBO PER FT LBR		Fiber & plow plcmt		60	
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt			
		SEB6-22		BSW-6 & plow plcmt			
		BM2(5/8)(8)		Ground Rod			
		Trip Charge		Trip Charge		1	
		Permit		Permit		1	
Nearest cross st.				Plat Page		Map#	
Originated By:		Ryan Einerwold		Date:		Completed By:	
Authorized By: (APS)				Date:		Inspected By:	
Authorized By: (AOM)				Date:			
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			

