

Revised 1-15-2019				CMS#		19138543	
CenturyLink BSW Order/Maintenance Work Authorization							
Company		T866 Exchange Name		MAPLE GROVE - MPGVMNXA		Service Order# 1548773792	
Work Activity		Fiber-Buried		Capital		Y Maintenance	
Customer Name		Scott Issacson		Phone#			
Address		17409 75th PI N		One Call Ticket#			
City & Zip		Maple Grove MN 55311					
Location/Directions							
Description of Work or Special Instructions							
Held Order		Y		Permit:		Y	
Tech Name and Tech #		Les Peterson		Employee Contact#		763-807-0943	
Sketch		Material/Labor Units		Footage/Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes		Comments	
Cntr Line foot		SEB3-22		BSW-3 & plow plcmt			
		SEB3-22T		BSW-3 & hand dig plcmt			
Ped# 1220-9015		SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		BSW guard at house		1	
		XXSEB-GL		Remove temp drop		Footage when temp can't be re-used	
Township:		BM61(1.25)SEB		BSW Bore footage		75	
Section		SEBO PER FT LBR		Fiber & plow plcmt			
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt		80	
		SEB6-22		BSW-6 & plow plcmt			
		BM2(5/8)(8)		Ground Rod			
		Trip Charge		Trip Charge		1	
		Permit		Permit		1	
Nearest cross st.		Jewel Ln		Plat Page		Map#	
Originated By:				Date:			
Authorized By: (APS)				Date:			
Authorized By: (AOM)				Date:			
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			