



Stub Conduit and wire above ground 5' from Xcel pole.  
Xcel will F&I pedestal to connect to Service Conductors.

Xcel OH Pole