

Revised 1-15-2019		CMS#		19208810 HELD	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T866	Exchange Name		Service Order#	1551278797
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	MST	Phone#	7633153426		
Address	10748 Trenton Ln N		One Call Ticket#		
City & Zip	Maple Grove, MN 55369, USA				
Location/Directions	GPS				
Description of Work or Special Instructions SEE SKETCH FOR DETAILS					
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	AA10109	Employee Contact#	763-228-8645		
Sketch		Material/Labor Units		Footage/Quantity	Comments
(Include Cntr Line & Pedes	Description	Notes			
Cntr Line foot	33	SEB3-22	BSW-3 & plow plcmt		
		SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	FIBER	SEPCUTOVER	CUTOVER BSW		
Parish/County		BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	NA	BM61(1.25)SEB	BSW Bore footage	260	
Section	NA	SEBO PER FT LBR	Fiber & plow plcmt	260	2-4 PORT MST
Range	NA	SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge	1	
		Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	NA		Plat Page	NA	Map# NA
Originated By:	AA10109	Date:	11/1/19	Completed By:	
Authorized By: (APS)		Date:		Inspected By:	
Authorized By: (AOM)		Date:			
Email sketch to: MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker			