

Cable replacement
Due to cable fault
under driveway

CAP 40 SD

6777

Ridglock Primary fault

10-27-19

~~W. Lock~~

WO# 899415

Jon L

