

Revised 2-10-2020	State MN	Contractor MN Metro	CMS#	20049668 HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name MPGVMNXA	Service Order#	1569703732	
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	Russell Cook	Phone#		
Address	10799 Sundance Blvd.	One Call Ticket#		
City & Zip	Maple Grove, MN 55369			
Location/Directions				
Description of Work or Special Instructions				
Held Order	Y	Permit:	Y	Bore:
Tech Name and Tech #	Employee Contact#		763-807-0943	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	130	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	45	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	108th Ave	Plat Page		Map#

A0H7T

Buried fiber 130' easement bore and 45' hand bury

Sundance Blvd N

10827

10799 Sundance Blvd

Originated By:		Date:		Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			