


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	Phil Setala	Phone#	(763) 416-2326	
Address	7611 Urbandale Ln N	One Call Ticket#		
City & Zip	Maple Grove MN			
Location/Directions				
Description of Work or Special Instructions	Plow 140 ft of fiber from ped to nid. 90 ft right of way bore required not plowed to corret ped			

Held Order	N	Permit:	Y	Bore:	Y	CBR#	6123091429
Tech Name and Tech #	Don Evans	Employee Contact#	6124303133				
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW	1				
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop	1	Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	85				
Section	SEBO PER FT LBR	Fiber & plow plcmt	50				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	Trip Charge	Trip Charge	1				
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.		Plat Page		Map#			



Originated By:	Don Evans	Date:	6/9/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	