

Revised 2-10-2020	State MN	Contractor MN Metro	CMS#	20157259
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name MPGVMNXA	Service Order#		
Work Activity Fiber-Buried	Capital	Maintenance	Y	
Customer Name Tom Reinardy	Address 9837 103rd Pl N	Phone#	(763) 424-9698	
City & Zip	Maple Grove MN			
Location/Directions	***** CURRENT CUSTOMER*****			
Description of Work or Special Instructions	Plow 160 ft of fiber from ped to nid. 110 ft righth of way bore required			
Held Order	N	Permit: Y	Bore: Y	CBR# 6127301001
Tech Name and Tech # Don Evans	Employee Contact#	6124303133		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	110	
Section	SEBO PER FT LBR	Fiber & plow plcmt	50	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.		Plat Page		Map#

Originated By: Don Evans	Date: 9/2/20	Completed By: _____	Date: _____
Authorized By: (SRO) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (MRO) _____	Date: _____	_____	_____

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker