

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name HAML MN HB	Service Order# T23046067
Work Activity Fiber-Buried	Capital Y	Maintenance N
Customer Name Pattee, Ben	Address 6370 Ranier Ln N	Phone# 763-478-0325
City & Zip Maple Grove, 55311	One Call Ticket#	
Location/Directions		
Description of Work or Special Instructions		

Held Order	N	Permit: Y	Bore: Y	CBR# 612-730-1378
Tech Name and Tech # Tom Springer #350	Employee Contact# 612-990-9926			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped# F6350	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop	450	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	50	
Section	SEBO PER FT LBR	Fiber & plow plcmt	50	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	150	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st. Shadyview and 64th pl n			Plat Page	Map#



Originated By: Tom Springer	Date: 5/4/21	Completed By:	Date:
Authorized By: (SRO) Heidi Clark	Date: 5/4/21	Inspected By:	Date:
Authorized By: (MRO)	Date:		

1. Distance of the bury in Right-of-Way	200	3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline	33	4. Nearest State Hwy mile marker	