

Zahn Design Comcast

JT 22232

Issued T-Ray 1/6/17 3241

Plant Maintenance Reque		: <b>V5</b>		Job	number	Hadso NW41
Node	dc151c	City	maple grov	/e	Date	11/20/2016
Address	10034	cottonwood In	C	ross Street	•	100th ave
Maint t	ech Name:	Shane Husbyn	Tech #	1342	Phone:	651-387-4988
Span type	✓ span (temped)	Span (no temp)	Digup	Other	Covine	-
Priority		er Impacting Issue b.) Vulne			Spring	i
2 a.) Aerial temp cables b.) Any temp - no liability issues						
3 a.) Identified cables - no customer impact b.) Leaks - no customer impact						
Work is needed: ASAP Normal						
Work is a:   Cable Replacement Broken Lashing Pole Transfer Damaged Ped						
Utility Violation Storm Damage Leakage Other						
MDU? (Attachments, lockboxes, cable on the roof)						
Type of Cable Aerial UG Bare UG Duct Self Support Size: 625						
Footage: Aerial Underground 324'						
Bore Required Yes No If yes, what type and how many 2 road and 2 driveways						
Is there fiber in the package?						
Cause for referral: RTM Leakage Rapid Resolve (Flux) Damage/Outage NH/MH LPI						
Cause for referral:						
Conservation of the conser						
Explain Damage:						
multiple faults on span. Full span replacement. 15 db low with bit errors. Customer impacting						
Date Received  Capitol Yes No Maint complete						
Total Tech			Capito Techs		No	Maint complete
Total Tech	-			-	"	
A Highlighted plant map must be attached						
To help expedite this maintenance request, information on this form needs to be filled out completely and						
signed by a technician and a supervisor requesting the repair.						
			,			
Tech Signat	ture Sh	ane Husbyn		Tech #	1342	Date11/20/2016
Supervisor	Signature			<b>→</b> 7)		
Construction Department Use Only						
Date received Project # Construction Completed  Coordinator Signature Supervisor Signature						
Coordinato	i Signature		Supervisor	r Signature		