

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	OSSEMNXO	Service Order#	na	
Work Activity	Fiber-Buried	Capital	N	Maintenance	Y
Customer Name			Phone#	na	
Address	10540 nathan ln n		One Call Ticket#		
City & Zip	maple grove, mn				
Location/Directions	gps				
Description of Work or Special Instructions	see sketch				

Held Order	N	Permit:	Y	Bore:	Y	CBR#	na
Tech Name and Tech #	AA10109		Employee Contact#	7632288645			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	see sketch	SEPCUTOVER		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop	200	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	70	
Section	SEBO PER FT LBR	Fiber & plow plcmt	120	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	see sketch		Plat Page	Map#



Originated By:	AA10109	Date:	10/1/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	