


Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	22140901-HELD
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	STMCMNXS			Service Order#	
Work Activity	Drop-Buried Copper		Capital	Y	Maintenance	
Customer Name	Jay & Colleen LeMay			Phone#	763-497-3996	
Address	9762 Monticello Ln N			One Call Ticket#		
City & Zip	Maple Grove, MN					
Location/Directions						
Description of Work or Special Instructions	Total 3 pr copper placement of 135' w/ a 82' bore. Dig and cut to N of concrete and then put buried splice. Unable to get all the way to the NID due to concrete. Cut in multiple locations by sprinkler install next door.					
Held Order	Y	Permit:	Y	Bore:	Y	CBR# 763-567-3800
Tech Name and Tech #	Kris Townsend			Employee Contact#	612-715-9069	
Sketch	Material/Labor Units			Footage/Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		135		
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	A0NM6	SEPCUTOVER		1		
Parish/County	BM83	BSW guard at house				
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		82		
Section	SEBO PER FT LBR	Fiber & plow plcmt				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt				
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	SEBO-COIL	Fiber Coil			Coil excess on Fiber drop add 1 unit	
	Permit	Permit		1	Any placement within the ROW requires a permit	
Nearest cross st.	98th Ave N Maple Grove			Plat Page	Map#	



Dig up and splice before concrete.

Originated By:	Kris Townsend	Date:	9/14/22	Completed By:	_____	Date:	_____
Authorized By: (SRO)	_____	Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)	_____	Date:	_____		_____		_____
Email sketch to:							

1. Distance of the bury in Right-of-Way	_____	3. Distance to the nearest intersection	_____
2. Distance from the terminal to the centerline	_____	4. Nearest State Hwy mile marker	_____