


Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	22147358
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	MPGVMNXA			Service Order#	
Work Activity	Fiber-Buried	Capital		Maintenance	Y	
Customer Name	Lisa Riskedahl			Phone#	150-000-1389	
Address	12021 84th way N			One Call Ticket#		
City & Zip	Maple Grove, MN					
Location/Directions						
Description of Work or Special Instructions	hand dig 110' from ped to nid. This is replacing a damaged drop to the home. Cut over. QF drop Im not sure on needing a permit. I listed it to be safe. It is in the back easment. Temp line on top of ground.					
Held Order	N	Permit:	Y	Bore:	N	CBR# 612-270-4825
Tech Name and Tech #	Kris Townsend			Employee Contact#	612-715-9069	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	A0NM6	SEPCUTOVER	CUTOVER BSW	1		
Parish/County		BM83	BSW guard at house	1		
Township:		XXSEB-GL	Remove temp drop		Footage when temp can't be re-used	
Section		BM61(1.25)SEB	BSW Bore footage			
Range		SEBO PER FT LBR	Fiber & plow plcmt			
		SEBO PER FT LBR T	Fiber & hand dig plcmt	110		
		SEB6-22	BSW-6 & plow plcmt			
		BM2(5/8)(8)	Ground Rod			
		SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit	
		Permit	Permit	1	Any placement within the ROW requires a permit	
Nearest cross st.	Jonquil Ln N Maple Grove			Plat Page	Map#	



Originated By:	Kris Townsend	Date:	9/26/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	