


CenturyLink BSW Order/Maintenance Work Authorization

Company		Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital		Maintenance	Y
Customer Name	tom peterson		Phone#	(763) 420-3927	
Address	8687 peony ln n		One Call Ticket#		
City & Zip	maple grove				
Location/Directions					
Description of Work or Special Instructions	plow 60 ft south to other side of driveway. Dig up drop and put a burird splice on it. 30ft drivewa driveway bore				

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	7634203927	
Tech Name and Tech #	nathe					Employee Contact#					

Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt	60	
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	889-9058	SEPCUTOVER		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	30	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit		Any placement within the ROW requires a permit

Nearest cross st.	weaver lake road	Plat Page		Map#	
-------------------	------------------	-----------	--	------	--



Originated By:	nathe	Date:	10/19/22	Completed By:	_____	Date:	_____
Authorized By: (SRO)	_____	Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)	_____	Date:	_____		_____		_____

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0