

Overview

Construction Notes:

Replacing damaged span of cable on behalf of Comcast.

Directional boring approximately 231' on ROW from

Comcast Ped located infront of 7324 Niagara Ln N, south to

Comcast ped located at 7300 Niagara Ln N. Potholing where
necessary to identify existing utilities.

Method: 2" directional bore (231')

Conduit: 2" PVC conduit Cable: .625 coaxial cable

| On site POC: | | | | | |
|--------------|--|--|--|--|--|
| Name: | | | | | |
| Phone: | | | | | |
| Email: | | | | | |



