


Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	23140345
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name OSSEMNXO	Service Order#	24414025	
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	KEITH HARDER	Phone#		
Address	10835 101ST PL N	One Call Ticket#		
City & Zip	MAPLE GROVE, MN 55369			
Location/Directions				
Description of Work or Special Instructions				

Held Order	N	Permit:	Y	Bore:	Y	CBR#	
Tech Name and Tech #	Mamadee Keita - AD22553			Employee Contact#	404-317-5848		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW	1				
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	119				
Section	SEBO PER FT LBR	Fiber & plow plcmt	49				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit			
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.			Plat Page		Map#		



Originated By:	MAMADEE KEITA	Date:	9/19/23	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					