



Replace HH 1368-HH16.

P.242083.C.50  
PLCF - HH 30x48x36 SPLIT LID 2 - 1 unit  
HH 30x48x36 - 1 unit

P.242083.C.51  
RMV HH - 1 Unit

47  
2001  
XXXXXX048  
9-52 NC (Fibers: 1-4)  
NC (Fibers: 5-8)  
10) P1\_37-38 (Fibers: 9-10)  
20 NC (Fibers: 11-20)  
9 NC (Fibers: 21)  
25 NC (Fibers: 22-25)  
P1\_74-75 NC (Fibers: 26-27)  
[REV]P1A,74-75 NC (Fibers: 28-29)  
A,30-31 NC (Fibers: 30-31)  
P1\_81 NC (Fibers: 32)  
A,33 NC (Fibers: 33)  
P1\_83 NC (Fibers: 34)  
A,35-36 NC (Fibers: 35-36)  
P1\_85-86 NC (Fibers: 37-38)  
A,39-48 NC (Fibers: 39-48)  
->WEAVERDUNKPK, 1-> ->4.967101duplca,1->

100102  
1368H16  
13.00(2001)  
0000000001\_30824

72659  
298' 1996  
EWOMGR\_25\_24  
PLBC  
176,28-41 (Pairs: 1-16)  
A,17-22 (Pairs: 17-22)  
176,48-49 (Pairs: 23-24)

6085  
6085

