



WO# 867598  
 Bore in approx. 1300'  
 of primary cable to  
 replace existing  
 faulted cable in  
 P.V.U.