

Revised 1-15-2019				CMS#		19159099	
CenturyLink BSW Order/Maintenance Work Authorization							
Company		T866 Exchange Name		MAPLE GROVE - MPGVMNXA		Service Order#	
Work Activity		Fiber-Buried		Capital		Y Maintenance	
Customer Name		Kyle Wimmer		Phone#		7633152988	
Address		15301 108th PI N		One Call Ticket#			
City & Zip		Maple Grove Mn					
Location/Directions							
Description of Work or Special Instructions				Plow 125 ft of fiber from ped to nid. 75 ft right of way bore required			
Held Order		N		Permit:		Y	
Tech Name and Tech #		Donald Evans		Employee Contact#		612-430-3133	
Sketch		Material/Labor Units		Footage/Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes		Comments	
Cntr Line foot		SEB3-22		BSW-3 & plow plcmt			
		SEB3-22T		BSW-3 & hand dig plcmt			
Ped#		SEPCUTOVER		CUTOVER BSW		1	
Parish/County		BM83		BSW guard at house		1	
		XXSEB-GL		Remove temp drop		1 Footage when temp can't be re-used	
Township:		BM61(1.25)SEB		BSW Bore footage		75	
Section		SEBO PER FT LBR		Fiber & plow plcmt			
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt		50	
		SEB6-22		BSW-6 & plow plcmt			
		BM2(5/8)(8)		Ground Rod			
		Trip Charge		Trip Charge		1	
		Permit		Permit		1 Any placement within the ROW requires a permit	
Nearest cross st.				Plat Page		Map#	
Originated By:		Donald Evans		Date:		9/12/19	
Authorized By: (APS)				Date:			
Authorized By: (AOM)				Date:			
Email sketch to:				MetroBSW@Centurylink.com			
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			