

Revised 1-15-2019

CMS#


20019241 - HELD

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name	OSSEO - OSSEMNXO	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	Y
Customer Name	Kristopher Stein			Phone#	7633150702
Address	10220 Nathan Ln n			One Call Ticket#	
City & Zip	Mpale Grove Mn				
Location/Directions					
Description of Work or Special Instructions	Bore 200 ft of fiber from ONU and place 2 port MST				

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	5073838932
Tech Name and Tech #	Donald Evans			Employee Contact#	612-430-3133		

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	250	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.			Plat Page	Map#



Originated By: Donald Evans Date: 9/18/19 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	