


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	Service Order#
Work Activity	Fiber-Buried	Capital <input type="checkbox"/> N Maintenance <input type="checkbox"/> Y
Customer Name	NIC SIENKO	Phone# (763) 493-0040
Address	8050 ARROWWOOD LN N	One Call Ticket#
City & Zip	MAPLE GROVE, MN 55369	
Location/Directions	gps	
Description of Work or Special Instructions	place 70' fiber with 40' bore to nid from mst. Picking up 200' temp fiber. BM83 tiwrapped to temp fiber at location	

Held Order	<input type="checkbox"/> N	Permit: <input type="checkbox"/> Y	Bore: <input type="checkbox"/> Y	CBR#	763-458-3094
Tech Name and Tech #	aa10109	Employee Contact#	7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments	
	Description	Notes			
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt			
	SEB3-22T	BSW-3 & hand dig plcmt			
Ped#	A0P28	SEPCUTOVER	1		
Parish/County	BM83	BSW guard at house			
	XXSEB-GL	Remove temp drop	200	Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage	40		
Section	SEBO PER FT LBR	Fiber & plow plcmt	70		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt			
	SEB6-22	BSW-6 & plow plcmt			
	BM2(5/8)(8)	Ground Rod			
	Trip Charge	Trip Charge	1		
	Permit	Permit	1	Any placement within the ROW requires a permit	
Nearest cross st.		Plat Page		Map#	



Originated By:	aa10109	Date:	9/16/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	