


**CenturyLink BSW Order/Maintenance Work Authorization**

Company	Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	eli kahn		Phone#	(150) 002-2899
Address	8095 arrowood ln n		One Call Ticket#	
City & Zip	maple grove			
Location/Directions	pp			
Description of Work or Special Instructions	place 80ft of fiber drop with 27ft of bore driveway unable to create bsw for this address>			

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	9172094896
Tech Name and Tech #	nathe				Employee Contact#	6127159213				

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	AoPC5	SEPCUTOVER	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	27	
Section	SEBO PER FT LBR	Fiber & plow plcmt	80	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	82nd ave		Plat Page	Map#



Originated By:	nathe	Date:	7/29/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0