

# Forced Relo 10325 Troy Ln N. Maple Grove, 55311

**JB0001338761**

Node: MNMGD01F00

Legacy: N/A

PED (NEW)		(EXISTING)		UTILITY POLE	
VAULT (NEW)		(EXISTING)		LOCK BOX, JUNCTION BOX	
NEW UG PLACEMENT				UTILITY, MECHANICAL, DATA ROOM	
EXISTING CONDUIT				FOOTAGE	
AERIAL PLACEMENT				SPLICE CASE	
INTERNAL PLACEMENT				FIBER PANEL	
.860 CABLE				BUILDING ADDRESS	
.715 CABLE					
TAP (2-PORT)					
TAP (4-PORT)					
TAP (8-PORT)					

### \*Construction Notes\*

Road construction crew hit our duct, pulled out existing vault, and damaged the fiber. Xcel is setting new poles 20' east of existing. Michels will be setting a vault/case location 20' east of existing. USI will extend duct from existing vault location to new proposed vault/case location, and pull new 48ct fiber from existing case location to new proposed vault/case location. USI aerial crew will transfer a pole, frame new pole, riser to new proposed vault/case and shuffle slack for new case.



Directional Drilling for Placement of (2) 2" Conduits

Aerial Placement - Delash/Relash Fiber - Shuffle Slack - Existing Attachments

Vacuum Excavate for Placement of (2) 2" Conduits

Installation of New 36" x 48" Fiber Vault \*to be performed by Michels\*

Installation of New 36" x 48" Fiber Vault

Pulling Through Existing Conduit

Existing Fiber Vault Location

6'

Immanuel United Methodist Church

Creative Homes - Evanswood

Immanuel United Methodist Cemetery

Create Construction

100th Ave N

100th Pl N

101st Ave N

101st Ave N

101st Ave N

Brockton Ln N

Walnut Grove Ln N

Troy Ln N

Olive Ln N

Stoney Creek Landscape Design