


Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	22175801
-----------------------	-------	----	------------	----------	------	----------

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	Ted Lyons	Phone#	150 005 9810	
Address	10024 107th PL N	One Call Ticket#		
City & Zip	Maple Grove, MN 55369			
Location/Directions	xxxxx			
Description of Work or Special Instructions	Total fiber placement of 206' with a 127' bore. Cut over when done.			

Held Order	N	Permit:	Y	Bore:	Y	CBR#	612 669 6900
Tech Name and Tech #	Nation		Employee Contact#	6515290847			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	xxxxx	SEPCUTOVER	1	
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop	300	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	127	
Section	SEBO PER FT LBR	Fiber & plow plcmt	206	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	Nathan Ln N		Plat Page	Map#



Originated By:	Jonas Nation	Date:	11/18/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0