


Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	22177542
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name MPGVMNXA	Service Order#		
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	Samuel Kim	Phone#		150 007 0889
Address	17353 75th PL N	One Call Ticket#		
City & Zip	Osseo, MN 55311			
Location/Directions	xxxxx			
Description of Work or Special Instructions		Total fiber placement of 151' with a 97' bore. Cut over when done.		

Held Order	N	Permit:	Y	Bore:	Y	CBR#	612 567 2808
Tech Name and Tech #	Nation		Employee Contact#		6515290847		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW	1				
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop	400	Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	97				
Section	SEBO PER FT LBR	Fiber & plow plcmt	151				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit			
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.	Jewel Ln N		Plat Page	Map#			



Originated By:	Jonas Nation	Date:	11/23/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0