

CenturyLink Constant Job Order/Maintenance Work Authorization


Company: T866 Exchange: 579 Osseo Service Order#: _____
 Work Activity: **Drop-Buried Copper** Capital: Maintenance: _____
 Customer Name: Morris DUPREE Phone#: 763-416-3875
 Address: 9608 105TH AVE N MAPLE GROVE MN One Call Ticket#: _____
 Location/Directions: _____
 Description of Work or Special Instructions: _____

DOR/TOG: Yes ___ No Permit: Yes ___ No Bore: Yes ___ No CBR#: 612-248-4725
 Employee Name: _____ Employee Contact#: 612-219-9122

Sketch (Include Line & Pedestal)	Material/Labor Units		Est	Actual	Placed by (Foreman/Crew Name)
	Description	Notes	Qty.	Qty.	
Line					
Ped#					
Parish/County					
Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____

SKETCH _____ Tax Code _____
 135 feet total



Originated By: _____ Date: _____ Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____