
4/21/17

IT. 23827 T-RRY Perint

Comcast

Plant Maintena	ance Request	V4		Job number	NW510		
Node DA1	L41	City	Maple Grove	Date	4/18/2017		
Address	18023	82nd Ave	Cross	Street	82nd Way		
Maint tech	Name:	Eric Classen	Tech #	1346 Phone:	651-387-7078		
					. .		
Span type 🗌	span (temped)	✓ Span (no temp)	Digup	Other Spring			
Priority 1	a.) Customer	Impacting Issue b.) Vuli	nerabe temp c.) TIE rel	ated ticket	1		
2 a.) Aerial temp cables b.) Any temp - no liability issues							
3							
Work is needed	-	✓ Normal		94 - 22	-		
Work is a:	=0 <u> </u>	2-1 /4					
	Utility Viola	ation Storm Dama		Other	_		
,		es, cable on the ro	·,	✓ No			
Type of Cable	Aerial	UG Bare UG Du	ct Self Support	Size	625		
Footage:	Aerial		Underground	278'			
					load bore across 82nd Ave		
Is there fiber in	the package?	☐ Yes ✓ No	How Many Fibe	rs?	_		
Cause for referral: RTM Leakage Rapid Resolve (Flux) Damage/Outage NH/MH							
(check one)	Priorit	y plant fault	LPI Service	e Call Alert PI	Ticket Other		
Explain Damage:							
Line is damaged at 165' from the 17 value tap which wheeled off to directly under the road. Line will need to be							
replaced to fix the flux issue.							
		<u>Mainte</u>	nance Departme				
Date Received			Capitol	Yes No	Maint complete $\ igsqcup$		
Total Tech Hou	rs		Techs				
				one measured vectors are seened in			
- 1 1 10			plant map must b				
• •		•		m needs to be fille	ed out completely and		
signed by a teci	nnician and a s	upervisor requesti	ng the repair.				
Tech Signature	Fric	Classen	Ter	ch # 134	5 Date 4/18/20	∩1 <i>7</i>	
Supervisor Sign		Classell		154	- 4/10/20	<u></u>	
Supervisor Sign			-				
		Constr	uction Departme	nt Use Only			
Date received		Project		int Ose Only	Construction Completed		
Coordinator Sig	nature ——	Troject	" Supervisor Sigi	nature	_ +5.15ti dation completed		
Coordinator Sig			- Juhei Aigoi Jigi	iatui e		_	



.