

| | | | | | |
|--|-------------------|------------|--------------------|------------------------|---------------------|
| Local Exch# | | CMS# | | 17083136 HELD / PERMIT | |
| CenturyLink BSW Order/Maintenance Work Authorization | | | | | |
| Company | T600 | Exchange | Service Order# | 1436442187 | |
| Work Activity | Capital | Y | Maintenance | N | |
| Customer Name | DARCIE MATHWIG | | Phone# | 763-420-1022 | |
| Address | 10393 108TH AVE N | | One Call Ticket# | | |
| City & Zip | MAPLE GROVE | | | | |
| Location/Directions | GPS | | | | |
| Description of Work or Special Instructions | | | | | |
| PALCE 150' FIBER DROP TO NID FROM DOG HOUSE WITH 20' DW BORE | | | | | |
| Held Order ? | NO | Permit: | NO | Bore: | NO |
| Employee Name | MER064519 | | Employee Contact# | 7632288645 | |
| Material/Labor Units | | | Est | Actual | Placed by |
| (Include Cntr Line & Pedestal) | Description | Notes | Qty. | Qty. | (Foreman/Crew Name) |
| Cntr Line foot# | 33 | SEB3-22 | Place 3 pair BSW | | |
| Ped# | 124711 | SEPCUTOVER | CUTOVER BSW | | |
| Parish/County | Hennepi | BM83 | BSW guard at house | | |
| | | XXSEB-GL | Remove temp drop | | |
| Township: | na | BM61(1.5)D | BSW Bore required | | |
| Section | na | SEB3-22T | Hand Dig | | |
| Range | na | SEBOP2 | Fiber Drop | | |
| Nearest cross st. | GPS | Plat Page | GPS | Map# | GPS |
| Damaged facility # | | | | | |

SKETCH



| | | | | | | | |
|--|-----------|---|---------|---------------|--|-------|--|
| Originated By: | MER064519 | Date: | 4/20/17 | Completed By: | | Date: | |
| Authorized By: (APS) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (AOM) | | Date: | | | | | |
| Inspection Notes: | | MetroBSW @centurylink.com | | | | | |
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | | | | | |
| 2. Distance from the terminal to the centerline: | | 4. Nearest State Hwy mile marker | | | | | |