



Local  
CMS#

CMS#

17089205 PERMIT


**CenturyLink Constant Job Order/Maintenance Work Authorization**

Company T866 Exchange 579 Osseo Service Order# \_\_\_\_\_  
 Work Activity Drop-Buried Copper Capital x Maintenance \_\_\_\_\_  
 Customer Name DARREN MARICH Phone# 763-315-1106  
 Address 17134 76TH PL N MAPLE GROVE MN One Call Ticket# \_\_\_\_\_  
 Location/Directions \_\_\_\_\_  
 Description of Work or Special Instructions \_\_\_\_\_

DOR/TOG Yes \_\_\_ No x Permit: Yes \_\_\_ No x Bore: Yes \_\_\_ No X CBR# 612-803-5937  
 Employee Name \_\_\_\_\_ Employee Contact# 612-219-9122

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County _____					
Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_  
 Damaged facility # \_\_\_\_\_ Tax Code \_\_\_\_\_  
**SKETCH** -N-



Originated By: \_\_\_\_\_ Date: \_\_\_\_\_ Completed By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (APS) \_\_\_\_\_ Date: \_\_\_\_\_ Inspected By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (AOM) \_\_\_\_\_ Date: \_\_\_\_\_  
 Inspection notes: \_\_\_\_\_