



Local  
CMS#

CMS#

17097045 PERMIT


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# \_\_\_\_\_  
 Work Activity Drop-Buried Copper Capital x Maintenance \_\_\_\_\_  
 Customer Name TRAVIS ANDERSON Phone# 763-391-0296  
 Address 10615 BOUNDARY CREEK TERR N One Call Ticket# \_\_\_\_\_  
 Location/Directions maplegrove mn  
 Description of Work or Special Instructions plow 235ft from ped to nid,this is fiber. Pick up 400ft temp when done. Cus sprinklers

DOR/TOG Yes \_\_\_ No x Permit: Yes \_\_\_ No x Bore: Yes \_\_\_ No x CBR# 612-865-8229  
 Employee Name Steve Winch Employee Contact# 612--387-0921

Sketch (Include Line & Pedestal)	Material/Labor Units		Est	Actual	Placed by (Foreman/Crew Name)
	Description	Notes	Qty.	Qty	
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_  
 Damaged facility # \_\_\_\_\_ Tax Code \_\_\_\_\_  
**SKETCH**



Originated By: Winch Date: 5/9/17 Completed By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (APS) \_\_\_\_\_ Date: \_\_\_\_\_ Inspected By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (AOM) \_\_\_\_\_ Date: \_\_\_\_\_  
 Inspection notes: \_\_\_\_\_