

17105739 OOS PERMIT

CenturyLink Constant Job Order/Maintenance


Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper Capital Maintenance
 Customer Name SAMANTHA PERKINS Phone# 763-424-1090
 Address 10310 97th PL N One Call Ticket#
 Location/Directions Maple Grove, MN 55369
 Description of Work or Special Instructions

DOR/LOG Yes No Permit: Yes No Bore: Yes No
 Employee Name Joe Vukelich Employee Contact# joe.vukelich
 CBR# 612-499-1044

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County					
Hamper					
Township					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH

No Temp hayed,
New Drop 230'



97th PL N

CUST EXISTING DROP IS BAD. CANT HAY TEMP. CUST NEEDS

DROP ASAP TO GET SERVICE.

Originated By: JOE VUKELICH Date: 5/20/11 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____