


Revised 5-23-17				CMS#		17112028 HELD / PERMIT					
CenturyLink BSW Order/Maintenance Work Authorization											
Company		T600		Exchange		OSSEO		Service Order#		MRMN2581233001A00	
Work Activity		Drop-Buried Copper				Capital		Y		Maintenance	N
Customer Name				LOUIS A HARLANDER				Phone#		7634250686	
Address				10245 YORKTOWN LN N				One Call Ticket#			
City & Zip		MAPLE GROVE, MN 553692858									
Location/Directions											
Description of Work or Special Instructions				Please rebury drop							
Held Order		Y		Permit: Y N		Bore: Y		CBR#		6513025304	
Employee Name				Dexter Koopp				Employee Contact#		6513025304	
Sketch		Material/Labor Units				Footage		Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes							
Cntr Line Footage		33		SEB3-22		BSW 3 pair					
Ped#				SEPCUTOVER		CUTOVER BSW					
Parish/County		Hennepin		BM83		BSW guard at house		1			
				XXSEB-GL		Remove temp drop					
Township:				BM61(1.25)SEB		BSW Bore footage					
Section				SEBO PER FT LBR		Fiber Drop		175			
Range				BM2(5/8)(8)		Ground Rod					
				SEB6-22		BSW 6 Pair					
Nearest cross st.		Zachary				Plat Page		Map#			



Originated By:	Dexter Koopp	Date:	5/30/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			