


Revised 5-23-17		CMS#		17118225 HELD / PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange	OSSEO	Service Order#	MRMN1258161001G00
Work Activity	Drop-Buried Copper		Capital	Y	Maintenance
Customer Name	Stephen Johnson		Phone#	7633150229	
Address	10401 106th PI N		One Call Ticket#		
City & Zip	Maple Grove 55369				
Location/Directions	Boundary Creek Terrace and 106th PI N				
Description of Work or Special Instructions	Please bury both msts, and plow drop to below second window from South east corner of house				
Held Order	Y	Permit:	Y	Bore:	Y
Employee Name	Dexter Koopp		Employee Contact#	6513025304	
Sketch	Material/Labor Units			Comments	
(Include Cntr Line & Pedestal)	Description	Notes	Footage	Quantity	
Cntr Line Foot#	33	SEB3-22	BSW 3 pair		
Ped#	375-9021	SEP CUTOVER	CUTOVER BSW		
Parish/County	Hennepin	BM83	BSW guard at house	1	
		XXSEB-GL	Remove temp drop		
Township:		BM61(1.25)SEB	BSW Bore footage	180	6 bores under driveways
Section		SEBO PER FT LBR	Fiber Drop	550	3
Range		BM2(5/8)(8)	Ground Rod		
		SEB6-22	BSW 6 Pair		
Nearest cross st.	Boundary Creek Terrace		Plat Page	Map#	



Originated By:	Dexter Koopp	Date:	6/7/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:				Date:	
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	