

# Comcast

## Plant Maintenance Request

v4

Job number

**NW536**

Node DB121

City

Maple Grove

Date

5/25/2017

Address 6580 E Fish Lake RD

Cross Street

Maint tech Name: Igor Romansov

Tech #

1542

Phone:

612-875-6743

Span type  span (temped)  Span (no temp)  Digup  Other  Spring

Priority 1  a.) Customer Impacting Issue b.) Vulnerable temp c.) TIE related ticket

2  a.) Aerial temp cables b.) Any temp - no liability issues

3  a.) Identified cables - no customer impact b.) Leaks - no customer impact

Work is needed:  ASAP  Normal

Work is a:  Cable Replacement  Broken Lashing  Pole Transfer  Damaged Ped

Utility Violation  Storm Damage  Leakage  Other

MDU? (Attachments, lockboxes, cable on the roof)  Yes  No

Type of Cable  Aerial  UG Bare  UG Duct  Self Support

Size: 875

Footage: Aerial \_\_\_\_\_ Underground 80'

Bore Required  Yes  No If yes, what type and how many \_\_\_\_\_

1 driveway

Is there fiber in the package?  Yes  No How Many Fibers? \_\_\_\_\_

Cause for referral:  RTM  Leakage  Rapid Resolve (Flux)  Damage/Outage  NH/MH

(check one)  Priority plant fault  LPI  Service Call Alert  PI Ticket  Other

### Explain Damage:

Damaged cable under driveway for 6580 E fish Lake RD; damaged cable is currently temped across the driveway; needs new partial under the driveway and then resplice on both sides; TDR shows fault 484ft from splice to the east

### Maintenance Department Use Only

Date Received \_\_\_\_\_ Capitol  Yes  No Maint complete

Total Tech Hours \_\_\_\_\_ Techs \_\_\_\_\_

### A Highlighted plant map must be attached

To help expedite this maintenance request, information on this form needs to be filled out completely and signed by a technician and a supervisor requesting the repair.

Tech Signature Igor Romansov Tech # 1542 Date 5/25/2017

Supervisor Signature \_\_\_\_\_

### Construction Department Use Only

Date received \_\_\_\_\_ Project # \_\_\_\_\_  Construction Completed

Coordinator Signature \_\_\_\_\_ Supervisor Signature \_\_\_\_\_

